

## DO NOT DRIVE

### Your new Nexon's DCT is likely experiencing low-speed jerking due to clutch engagement calibration or software issues.

Jerking can cause unpredictable vehicle behaviour, increasing accident risk, especially in traffic.

#### Diagnosis Summary

<b>Primary Fault</b>	DCT clutch engagement calibration issue
<b>Severity</b>	<b>HIGH</b>
<b>System Affected</b>	Drivetrain
<b>Problem Summary</b>	Your new Nexon petrol jerks at low speeds (below 20 km/h) when slowing down, feeling like the car might stall or the transmission is failing.
<b>Explanation</b>	The Dual Clutch Transmission (DCT) in your new Tata Nexon is exhibiting jerking at low speeds, particularly when slowing down and warm. This often points to an issue with the clutch engagement calibration or the Transmission Control Unit (TCU) software. At 700 km, it's highly unlikely to be wear, suggesting a manufacturing defect or initial software bug affecting smooth clutch operation during downshifts or low-speed crawling.

#### How It Happens

- Step 1: The DCT's software controls clutch engagement and disengagement during gear changes.
- Step 2: If the calibration is imperfect or a sensor provides incorrect data, the clutch might engage/disengage abruptly at low speeds.
- Step 3: This abrupt action causes the engine to momentarily lug or surge, resulting in the jerking sensation.
- Step 4: The issue becomes more noticeable when warm as transmission fluid properties change and components expand.

#### If Left Unattended

- Accelerated wear on the DCT clutch plates, leading to premature failure
- Increased stress on transmission components and engine mounts
- Potential for complete transmission failure requiring costly replacement

#### Vehicle Assessment

<b>Driveability</b>	<b>Restricted — Short Distance Only</b>
<b>Safety Impact</b>	The jerking can cause unexpected deceleration or acceleration at low speeds, potentially leading to a rear-end collision or loss of control in tight traffic situations.
<b>Part Location</b>	The Dual Clutch Transmission (DCT) is located between the engine and the drive wheels, typically under the front of the vehicle.

*Disclaimer: This report is generated by VahanSense AI for informational purposes only and does not constitute professional mechanical advice. Diagnosis accuracy depends on the symptoms and information provided. Always consult a qualified mechanic before making repair decisions. Cost estimates are approximate and may vary by city, workshop, and vehicle condition. VahanSense is not liable for any decisions made based on this report.*

<b>Expected Lifespan</b>	1.0L km (premature)
<b>Local Context</b>	Kolkata's heavy stop-start traffic conditions put significant stress on DCTs, as they constantly engage and disengage clutches at low speeds. This environment can quickly expose any calibration issues or minor defects in the transmission's low-speed operation.

### Cascading Damage Risk

- Continued jerking will prematurely wear out the DCT clutch plates, potentially leading to a full clutch replacement costing ₹40,000-₹70,000.
- Excessive vibration and shock loads can damage transmission mounts and engine mounts, requiring additional replacements (₹5,000-₹15,000).
- In severe cases, the entire transmission unit could fail, necessitating a complete replacement which can cost upwards of ₹1.5-2 lakhs.

### Financial & Insurance

<b>Parts Strategy</b>	For DCT components, especially in a new vehicle, always insist on OEM (Original Equipment Manufacturer) parts from an authorised service centre. These are safety-critical and require precise calibration and integration with the vehicle's electronics.
<b>Insurance Coverage</b>	<b>Not Covered</b>
<b>Coverage Reason</b>	This issue is likely a manufacturing defect or a software glitch, which is not covered under standard comprehensive motor insurance, as it's not accidental damage.
<b>Claim Advice</b>	Do not claim insurance for this issue. It's a warranty claim for a manufacturing defect. Claiming would be denied and could affect your No Claim Bonus (NCB) unnecessarily. The repair should be free under warranty.

### Scam Shield — Watch Out For

- Be wary if the service centre immediately suggests a full clutch replacement without first attempting a software update or recalibration. For a 700 km car, this is highly unlikely to be the primary fix.
- Decline any suggestions for 'engine tuning' or 'fuel system cleaning' (typically ₹2,000-₹5,000) as these are unrelated to a transmission jerking issue.

### VahanSense Recommendations

- Visit an authorised Tata service centre immediately.
- Since your car is brand new (700 km), this issue should be covered under warranty.
- Request a TCU software update and clutch recalibration first.
- Drive very gently to the service centre, avoiding heavy traffic if possible.

### Questions to Ask Your Mechanic

- Can you check for any pending software updates for the DCT's Transmission Control Unit (TCU)?
- Will you perform a clutch learning or recalibration procedure after the software update?
- What diagnostic steps will be taken if the software update doesn't resolve the jerking?

### Alternative Diagnoses

*Disclaimer: This report is generated by VahanSense AI for informational purposes only and does not constitute professional mechanical advice. Diagnosis accuracy depends on the symptoms and information provided. Always consult a qualified mechanic before making repair decisions. Cost estimates are approximate and may vary by city, workshop, and vehicle condition. VahanSense is not liable for any decisions made based on this report.*

Fault	Severity
Transmission Control Unit (TCU) software glitch	MEDIUM
Faulty speed sensor input to TCU	MEDIUM
Engine misfire (less likely without warning light)	MEDIUM
Loose engine or transmission mounts	MEDIUM

*Disclaimer: This report is generated by VahanSense AI for informational purposes only and does not constitute professional mechanical advice. Diagnosis accuracy depends on the symptoms and information provided. Always consult a qualified mechanic before making repair decisions. Cost estimates are approximate and may vary by city, workshop, and vehicle condition. VahanSense is not liable for any decisions made based on this report.*